

MBCI fastener supplier is no longer manufacturing or stocking fastener #15B or #15C.

Fastener #15B will be replaced with fastener #210 that is 3" long.
Fastener #15C will be replaced with fastener #211 that is 4" long.
There is a price difference for the replacement fasteners. Please view our [MBCI Architectural Pricing](#) catalog for the current price listing.